

City of San Diego PURCHASE ORDER

PO No. 4500098328

Date: 03/09/2018 Page 1 of 3

Ship To:

City of San Diego Billing Contact for Delivery Address 4077 N Harbor Drive San Diego, CA 92101 Bill To:

PUD ACCOUNTS PAYABLE 9192 TOPAZ WAY SAN DIEGO CA 92123 **Billing Contact:** Noraloyda Rivera

Telephone:

E-Mail: NMRIVERA@SANDIEGO.GOV

Vendor: Trademark Hoist Inc

1369 Ridgeway Street Pomona CA 91768 Terms:

within 30 days Due net

Delivery Terms: FOB Destination

Buyer: Janet Polite

Telephone: 619-236-7017

 $\textbf{Vendor ID:} \ \ 10038336 \qquad \textbf{Telephone:} 909\text{-}455\text{-}0801 \quad \textbf{E-Mail:} \quad \text{mikem@trademark-hoist.com}$

E-Mail: JPolite@sandiego.gov

Line#	Item ID/Description Serv # Service Description		Del.Date	Quantity/Ord UoM	Unit Price/Prc Ud Conv Factor	oM Exte	Extended Price	
1	FY18 PS 2 - ADDITION	AL PARTS COST	06/30/2018	11,542.5 EA	1.00 EA	USD	11,542.50	
1	FY18 PS 2 - Additional Specific parts are here. Profi 3T/2 Air Hoist. Ca Number of Chain Stand Standard Rope Control. Weight with Standard L Air Pressure: 65-90 psi, Air Connection: G3/4 Lifting Speed with No L Minimum Headroom: 2' Overload Protection Sta Ex Classification accord 94/9/EEC As Standard: Ex II 2 GE From 07/01/17 to 06/30	parts Cost (30% Markup-Max) Line 291 a pacity: 3.2 Metric Tons (7,040 lbs) s: 2. Chain Size: 9 x 27 mm Standard Lif 6.5 ft. ift: 146 pds Air Consumption: 53-92 cfm titing Speed at Full Load: 6.6-9.8ft/min pad: 13.8-16.4ft/min 1.4 in hook to hook undard Top Hook Mount FEM/ISO 1 Bm/I ling to EC Directive on Hazardous Locati 0 IIA T4/II 3 GD 11B T4. /18 use R. Villa (619)692-4972	and the t; 10ft	11,542.5 EA	1.00 EA	USD	11,542.50	
	Deliver to: PS2 - 4077	I. Harbor Drive, San Diego, CA 92101						
	Non-Deductible Tax					USD	894.54	
***	Item completely delivered	ed						
2	FY18 PS 2 - ADDITION	AL PARTS COST	06/30/2018	641.25 EA	1.00 EA	USD	641.25	
	specific parts are here.	parts cost (30% Mark-up Max), line 291 a Lift 3 Ton 9mm Double Strand for 20ft o nal charge for over 10ft lift. /18						
		se R. Villa (619)692-4974 I Harbor Drive, San Diego, CA 92101						
	Non-Deductible Tax					USD	49.71	
***	Item completely delivered	ed						
3	FY18 PS 2 - ADDITION	AL PARTS COST	06/30/2018	506.25 EA	1.00 EA	USD	506.25	
	FY18 PS2 - Additional p	parts cost (30% Mark-up Max), line 291 a	nd the					
Notes: T	l he Terms and Conditior	s of this Purchase Order are availa	ble at http://sandiego	.gov/purchasing/	SEE L	AST F	PAGE	
		IMPORTANT!				TOT		
To ensui	re prompt payments.	PO # must appear on all shipm son at <i>Bill-To</i> address listed abo	nents and invoices:	all invoices must be	1 01		<i>/</i> \L	



City of San Diego PURCHASE ORDER

PO No. 4500098328

Date: 03/09/2018

Page 2 of 3

Line#	Item ID/Description Serv# Service Description	Del.Date	Quantity/Ord UoM	Unit Price/Prc Uo Conv Factor	m Exte	nded Price
	specific parts are here. Chain Box, 1.6_3.2T1/2, 13m Total Capa Optional Steels increase headroom Chain Container *Chain Cont From 07/01/17 to 06/30/18	•				
	Department Contact: Jose R. Villa (619)692-4974 Deliver to: PS2 - 4077 N Harbor Drive, San Diego, CA 92101					
	Non-Deductible Tax				USD	39.24
***	Item completely delivered					
4	FY18 PS 2 - ADDITIONAL PARTS COST	06/30/2018	5,690.25 EA	1.00 EA	USD	5,690.25
	FY18 PS2 - Additional parts cost (30% Mark-up Max), line 291 ar specific parts are here. Motor Trolley 3.2 Motorized Trolley, , Plea	ase				
	provide beam flange wigth when ordering (2.16-12.20 inch) Hoist fixed / lug mounted into trolley. Trolley speed at full load is 49.5ft per min. From 07/01/17 to 06/30/18					
	Department Contact: Jose R. Villa (619)692-4974 Deliver to: PS2 - 4077 N Harbor Drive, San Diego, CA 92101					
	Non-Deductible Tax				USD	441.00
***	Item completely delivered					
5	FY18 PS 2 - ADDITIONAL PARTS COST	06/30/2018	1,653.75 EA	1.00 EA	USD	1,653.75
	FY18 PS2 - Additional parts cost (30% Mark-up Max), line 291 ar specific parts are here. Spark Resistant Package for Hoist. Inclu copper plated bottom block & hook, Ex Classification with increas spark protection: EX II 2 GD IIC T4. From 07/01/17 to 06/30/18	ides				
	Note: Standard Hoist is suitable for Class 1 Division 2 environme: This optional packade increases the protection to Class 1 Division environments.					
	Department Contact: Jose R. Villa (619)692-4974 Deliver to: PS2 - 4077 N. Harbor Drive, San Diego, CA 92101					
	Non-Deductible Tax				USD	128.17
***	Item completely delivered					
6	FY18 PS 2 - ADDITIONAL PARTS COST	06/30/2018	2,092.5 EA	1.00 EA	USD	2,092.50
	FY18 PS2 - Additional parts cost (30% Mark-up Max), line 291 ar specific parts are here. Spark Resistant package for 3 Ton trolley includes bronze trolley wheels. Ex classification with increased s protection: EX II 2 GD IIC T4. From 07/01/17 to 06/30/18					
	Department Contact: Jose R. Villa (619)692-4974 Deliver to: PS2 - 4077 N Harbor Drive, San Diego, CA 92101					
	Non-Deductible Tax				USD	162.17
***	Item completely delivered					
7	FY18 PS 2 - ADDITIONAL PARTS COST	06/30/2018	2,841.75 EA	1.00 EA	USD	2,841.75
	FY18 PS2 - Additional parts cost (30% Mark-up Max), line 291 ar specific parts are here. 5 Button Single Speed (all funct) pendant					
Notes: T	he Terms and Conditions of this Purchase Order are availab	le at http://sandiego	.gov/purchasing/	SEE !	 ЛСТ	
	IMPORTANT!			SEE LA FOR		
0 ensur		ents and invoices:	all invoices must be	ruk	10	IAL
irected t	e prompt payments, PO # must appear on all shipme o <i>Billing</i> Contact person at <i>Bill-To</i> address listed abov	/e	an involoco must be			



City of San Diego PURCHASE ORDER

PO No. 4500098328

Date: 03/09/2018

Page 3 of 3

Line#	Serv#	Item ID/Description Service Description	Del.Date	Quantity/Ord UoM	Unit Price/Prc Ud Conv Factor	om Ext	ended Price
		al push button control station for variable spped and lower. Includes suitable control length. 7 to 06/30/18					
		ontact: Jose R. Villa (619)692-4974 2 - 4077 N Harbor Drive, San Diego, CA 92101					
	Non-Dedu	ctible Tax				USD	220.24
***	Item complete	y delivered					
8	FY18 PS 2 - AI	DDITIONAL PARTS COST	06/30/2018	1,474.5 EA	1.00 EA	USD	1,474.50
	specific parts a	dditional parts cost (30% Mark-up Max), line 291 an are here. Booser Valve 5/3 1/2" Control Valve to allof JDN control station to existing crane drive motors 7 to 06/30/18	ow				
		ontact: Jose R. Villa (619)692-4974 2 - 4077 N Harbor Drive, San Diego, CA 92101					
	Non-Deduc	ctible Tax				USD	114.27
***	Item complete	y delivered					
9	FY18 PS 2 - CI	RANE REPAIR	06/30/2018	4,350 EA	1.00 EA	USD	4,350.00
		rane repair, line 292, Labor to change out new hois r the Confined space at PS 2. r to 06/30/18	t with				
		ontact: Jose R. Villa (619)692-4974 2 - 4077 N Harbor Drive, San Diego, CA 92101					
	Insurance and	business tax certificate to be issued as may be red	quired.				
	(OA 46000030	019)					
***	Item completed	y delivered					
Notes: Th	he Terms and C	Conditions of this Purchase Order are availab	le at http://sandiego	.gov/purchasing/			
IMPORTANT!					Line Item Tot Tax	al \$ \$	30,792.75 2,049.34
To on	o prompt ===		onto and invelore	all invoices sever to			
o ensure directed t	e prompt payr o <i>Billing</i> Conta	ments, PO # must appear on all shipme act person at <i>Bill-To</i> address listed abov	ents and invoices; re	all invoices must be	PO Total	\$	32,842.09