

PT 111 E9
Inst Grades

Street Book

F.B. 734

734

89 40
 10 00
 17 00
 138 80
 12 780
 12 780
 12 780
 12 780
 12 780
 11 715
 113 880

MICROFILMED
 DEC 15 1964

284 12
 600
 1500
 800
 1700

229700

590
 770
 1360
 40

7500
 1500
 14700
 6

600
 170
 770
 49015
 1015
 11115

Atlantic

Atlantic St.

		below		
H St.	Manhole	0.0	grade	19' E. of W. line of Atl'ic. St on main line.
G St	"	6"	"	14' South of N line of G St.
F St	"	3"	"	center of street
E St	"	6"	"	" " "
D St.	"	0.0	"	" " "
C St	"	3"	"	" " "
B St	"	0.0	"	" " "
A St	"	0.0	"	" " "
A 3/4 St.	"		"	

California St.

H St		Below grade		on South Property line.	8
G St	Inspection.	0.0	"	"	1.1" OK.
F St	"	0.0	"	"	1' 1" OK.
E St	"	0.0	"	"	1' 0" OK
D St	"	0.0	"	"	1' 0" OK
C St	"		"	"	
B St	"		"	"	
A St	"	0.0	"	"	1' 0" OK
Ash St	Flush-tank.	0.0	"	"	
"	Large flush tank.				
Beech	Inspection	0.0	"	"	1' 5" OK.
Cedar	"	-8"	"	"	1' 3" OK

California St.

Date	Inspection	Below grade	South line	
		0.0	"	1' 1" OK
Fir	"	0.0	"	1' 1" OK
Grape	"	0.0	"	1' 0" O.K.
Hawth'n.	"	0.0	"	1' 7" O.K.
Ivy	"	0.0	"	1' 8" O.K.
Juniper	"	0.0.	35.0' south of Juniper St.	1' 0" OK

Arctic Street

Street		Below grade		
H				
G	Inspection	-0' 2"	"	on south line. 3' 0" T.D.
F	"	-0' 4"	"	" " " 2' 4" X
E	"	-0' 5"	"	" " " 2' 0" O.K.
D	"	0.0	"	" " " 2' 9" X
C	"	0.0	"	" " " 3' 1" X
B	"	0.0	"	" " " 1' 9" O.K.
A	"	-0' 4"	"	" " " 1' 8" O.K.
Ash	Flush-tank.	0.0	"	" " " (capacity)
Beech	Inspection.	-0' 4"	"	" " " 1' 9" O.K.
Cedar.	"	-0' 6"	"	" " " 1' 10" O.K.

Arctic Street.

Street		Below grade			
Date	Inspection	-0' 4"	"	south line of st	1' 9" OK
Fir	Flush-tank		"		
Grape	Inspection	0.0.	"	on west of Arctic - center of Grape st.	1.5" X
Hawthorn	Flush-tank	0.0	"	on south of Hawthorn	
	" "	0.0	"	" North "	
Ivy	Inspection	-18"	"	on <u>North</u> line Ivy.	1' 5" O.K
Juniper.	"				

India Street

Street		Below grade			
H	manhole		"	on west line of India, cent ^r of H	
G	inspection	- 3"	"	on south line street	2' 0" X
F	"	- 5"	"	" " " "	1' 6" OK
E	"	- 7"	"	" " " "	1' 0" OK
D	"	0.0	"	" " " "	2' 6" X
C	"	0.0	"	" " " "	2' 9" X
B	"	- 2"	"	" " " "	1' 11" OK
A	"	- 2"	"	" " " "	2' 0" OK
Ash	flush-tank.	0.0	"	" " " "	
"	manhole -				
Beech	inspection	- 2"	"	on south line of st.	1' 1" OK
Cedar	"	- 8"	"	" " " "	1' 2" OK

India Street

Street	below grade		
Date	inspection	- 3"	" south line of street 1' 2" OK
Fir	<u>flush-tanks</u>		on south of Fir
"			on <u>North</u> of Fir
Grape	inspection	0.0	" on west line of India center of Grape st. 1' 2" OK
Hawthorn	"	- 4"	" on south line of street 1' 1" OK
Ivy	"	- 4"	" " " " " 1' 0" OK
Juniper	"	- 4"	35.0 south of Juniper street 1' 4" OK

Columbia Street

Street		below grade			
H	flush-tank.	0.0	"		OK
G	inspection	- 6"	"	on south line.	1' 7" OK
F	"	- 4"	"	" " "	2' 5" X OK
E	"	- 6"	"	" " "	2' 2" X OK
D	"	0.0	"	" " "	2' 9" X
C	"	0.0	"	" " "	2' 9" X
B	"	0.0	"	" " "	2' 8" X OK
A	"	0.0	"		1' 8" OK
Ash	flush tank. manhole	0.0	"		
Beech	inspection	- 4"	"	on south line.	1' 1" OK
Cedar	"	- 5"	"	" " "	1' 1" OK

Columbia Street

Street		below grade			
Date	inspection	0.0	"	on south line.	1' 3" OK
Elm.					
Pin	flush-tank	0.0	"	" " "	
	" "	0.0	"	" north "	
Grape	inspection	0.0	"	on west line Columbia center of Grape street.	1' 3" O.K.
Hawthorn	" "	- 22"	"	on south line	0' 10" OK
Ivy	flush tank	0.0	"	" " "	
	" "	0.0	"	" north "	
Juniper	inspection	0.0.	"	on west line Columbia street center line of Juniper street	1' 1" OK

State Street

Street		below ground.	side			
I	manhole	0.0	"		50' north of I street; cent state.	OK
H	"	"	"		35' west of state; center of H st.	
G	inspection.	- 4"	"	"		1' 10" OK
F	"	- 6"	"	"	4' south of F. st.	1' 7" OK
E	"	- 5"	"	"		1' 10" X
D	"	0.0	"	"		2' 10" X
C	"	- 2"	"	"		1' 8" OK
B	"	- 11"	"	"		2' 2" X
A	"	- 2"	"	"		2' 10" X
Ash	flush-tank	0.0	"			

cover to bot -
tom of inspec.

Beech.

State Street

Street	Inspection	below grade.		
Beech	inspection	- 8" "		0' 11" OK
Cedar	"	- 3" "		1' 0" OK
Date	"	- 6" "		0' 10" OK
Elm	"	- 4" "	4' north P. Line.	1' 3" OK
Fir	"	- 3" "		1' 2" OK
Grape	"	- 6" "		1' 2" OK
Hawthorn	bush-tank		on south line Hawthorn	
"	"		" north " "	
Ivy	inspection	- 2" "		1' 3" OK
Juniper	"	y's set 35' west	of state on Juniper. inspection not built.	

Union Street

street		below grade			
I					
H	inspection			not found.	
G	"	-3"	"		2" X
F	"	-10"	"		1' 8" X
E	"	-4"	"		2' 2" X
D	"	0.0	"		1' 8" OK
C	"	-6"	"	3" E of center of street.	2' 0" X
B	"	0.0	"	" " "	0' 10" OK
A	"	0.0	"		1' 11" OK
"	flush tank				
"	" "				
Astc.	manhole	0.0	"		

Union Street

Street	Inspection	below grade	
Beech	inspection	- 2" "	1' 3" OK
Cedar	"	- 4" "	1' 2" OK
Date	"	- 6" "	1' 2" OK
Elm	"		
Fir	"	- 6" "	1' 1" OK
Grape	"		
Hawthorn	flush tank		
"	" "		
Ivy	inspection	0.6 "	1' 0" OK
Juniper			

south line
north line

Brant Street

S Street

Below grade

Hawthorn inspection

-4" "

0' 11" OK

Ivy

"

0.0 "

1' 2" OK

Juniper flush-tank

0.0

Albatross street

street

below grade.

Pin inspection

0.0 "

1' 2" OK

Grape "

-4" "

1' 0" OK

Hawthorn "

-4" "

1' 2" OK

Ivy flush-tank.

Front Street

street

below grade

I				
H	inspection	-6"	"	2' 2" X
G	"	-7"	"	1' 7" OK
F	"	-6"	"	opposite west p. line 2' 9" X
E	"	-4"	"	" " " 2' 0" X
D	"	-4"	"	6' south of D street. 1' 8" X
C	"	-6"	"	2' north of p. line. 1' 8" X
B	"	-6"	"	3' 0" X
A	"	-8"	"	1' 8" OK
Ash	"	-8"	"	0' 11" OK
Beech	"	-8"	"	3' 0" X

Front Street

Street		below grade	
Cedar	inspection.	- 8"	1' 1" OK
Date	"	- 8"	0' 10" OK
Elm	"	0.0	0' 11" OK
Fir	"	- 6"	1' 0" OK
Grape	"	- 6"	1' 0" OK
Hawthorn	"	- 9"	1' 1" OK
Ivy	"	- 12"	1' 0" OK
Juniper	"	- 24"	OK
Kalmia	"	- 18"	0' 10" OK
Laurel	flush-tank		95

First Street

Street		below grade		
J	manhole			
I	manhole	-3"	"	35 west of 7 st. st.
"	"			
H	inspection	-0.0	0.0	1' 2" OK
G	"	-6"	0.0	1' 1" OK
F	"	-4"	0.1	1' 4" OK
E	"	-6"	"	2' 6" X
D	"	0.0	"	2' 7" X
C	"	-5"	"	1' 8" OK
B	"	0.0	"	2' 2" X
A	"	-2"	"	1' 2" OK
Ash	"	0.0	"	1' 3" OK

First Street

Species	Inspection	Below grade	
Beech	inspection	-5"	1' 3" OK
Cedar	"	0.0	1' 6" OK
Date	"	-2"	0' 11" OK
Elm	"	-0.0	1' 2" OK
Fir	"	-2"	0' 11" OK
Grape	"	-7"	1' 1" OK
Hawthorn	"	3"	1' OK
Ivy	"	-2"	1' 0" OK
Juniper	flush-tank		

Second Street

Street	inspection	below grade		
I	inspection	0.0	"	on south line 1' 6" OK
H	"	2"	"	" " " 1' 1" OK
G	"	3"	"	" " " 1' 7" OK
F	"	2"	"	" " " 1' 5" OK
E	"	4"	"	" " " 1' 6" OK
D	"	3"	"	3' south of H street. 1' 6" OK
C	"	4"	"	on south line 2' 5" X
B	"	12"	"	" " " 2' 6" X
A	"	6"	"	" " " 1' 6" OK
Ash	"	2"	"	" " " 1' 0" OK
Beech	"	2"	"	" " " 2' 0" X

Second Street

Street		below grade			
Cedar	inspection	8"	"	on south line street	0' 10" OK
Date	"	3"	"	"	" 1' 0" OK
Elm	"	4"	"	"	0' 10" OK
Pin	"	3"	"	"	1' 3" OK
Grape	flush tank	0.0	"	south line Grape capacity	
"	"	0.0	"	north " "	"
Hawthorn	inspection			not in.	
Luy	"	12"	"	on south line	1' 3" OK
Juniper	manhole	0.0	"	"	OK
Kalmia	inspection	12"	"	"	1' 3" OK
Laurel	flush tank			"	" capacity

Third Street

Street		below grade			
K	manhole	0.0	"	35' north of K street	
J	"	0.0	"	35' west of 3rd street	
I	inspection	3"	"	on south line	1' 3" OK
H	"	3"	"	3' north of ^{line} H street	1' 4" OK
G	"	3"	"	on south line	1' 3" OK
F	"	4"	"	" " "	1' 4" OK
E	"	0.0	"	3' south of E street	1' 8" OK
D	"		"		
C	"	2"	"	on south line	1' 5" OK
B	"	0.0	"	" " "	1' 6" OK
A	"	2"	"	" " "	2' 0" X

Third Street

street		below grade			
Ash	inspection	2"	"	on south line street	1' 9" X
Beech	"	3"	"	" " " "	2' 0" X
Cedar	"	0.0	"	" " " "	2' 3" X
Date	"	8"	"	" " " "	2' 2" X
Elm	"	0.0	"	" " " "	1' 1" OK
Pin	"	3"	"	" " " "	1' 2" OK
Grape	flush tank			south line Grape capacity	
"	" "			North " " "	
Hawthorn	inspection			none	
Ivy	"			"	
Juniper	flush tank				capacity.

street	Fourth Street	below grade			
K.	manhole				
J	inspection	0.0	"	on south line	OK
I	"	0.0	"	" " "	X
H	"	0.0		3' south of H street	OK
G	"	0.0		on south line	X
F	"	0.0		4' south of F street	X
E	"	0.0		on south line	X
D	manhole	0.0		" " "	OK
C	"	0.0		" " "	OK
B.	inspection	0.0		" " "	1' 6" OK
A	"	0.0		" " "	X
Ash.	" "	0.0		" " "	X

street	Fourth Street	belonging to		
Beech	inspection	0.0	on south line	X
Cedar	"	0.0	" " "	X
Date	"	0.0	" " "	X
Elm	"	0.0	" " "	X
Pin	"	0.0	" " "	X
Grape	"	0.0	" " "	
Hawthorn	"	0.0	" " "	X
Ivy	"	0.0		
Juniper	flush tank		capacity	

street Fifth Street below grade
L flush tank 0.0

K man hole

18' East of west line of 5th Street

J inspection 0.0 " on south line 2' 0" X

I " 0.0 " " " " 2' 6" X

H " 0.0 " " " " 1' 9" OK

G " 0.0 " " " " 1' 7" OK

F " 0.0 " " " " 2' 4" X

E " 0.0 " " " " 1' 10" OK

D " 0.0 " " " " 2' 4" X

C " 0.0 " " " " 2' 10" X

B " 0.0 " " " " 2' 9" X

A " 4" " " " " 2' 6" X

street	Fifth Street	below grade				
Ash	inspection	0.0	"	on south line	2' 1"	X
Beech	"	0.0	"	" " "	2' 7"	X
Cedar	"	0.0	"	" " "	2' 5"	X
Date	"	0.0	"	" " "	2' 7"	X
Elm	"	0.0	"	" " "	2' 0"	X
Fir	"	0.0	"	" " "	1' 7"	
Grape	"	0.0	"	" " "	2' 2"	X
Hawthorn	"	0.0	"	" " "	2' 5"	X
Ivy	"	0.0	"	" " "	2' 0"	X
Juniper	manhole	0.0	"	" " "		OK
Kalmia	inspection	2'	"	" " "	1' 3"	OK
Laurel	"	15"	"	" " "	1' 1"	OK

street	Fifth Street	below grade		
Maple	inspection	0.0	"	on south line 1'6" OK
Nutmeg	"	4"	"	" " " 0'11" OK
Olive	"	12"	"	" " " 1'0" OK
Palm	"	11"	"	" " " 1'2" OK
Quince	flush tank	0.0	"	capacity

Street	Sixth Street	beton grade				
L	manhole					
K	"	0.0	"	35. west of 6th st, center of K st.		
J	inspection	0.0	"	on south line of street	2'	O.K.
I	"	0.0	"	" " " "	2'	O.K.
H	"	0.0	"	4' south of property	2'	O.K.
G	"	0.0	"	on south line	2' 4"	O.K.
F	"	0.0	"	4' south of property	2'	O.K.
E	"	0.0	"	on south line	1' 9"	O.K.
D	"	0.0	"	on south line	2' 0"	O.K.
C	manhole	0.0	"	" " "		O.K.
B	inspection	0.0	"	" " "	2'	O.K.
A	"	0.0	"	" " "	2' 6"	X

Street	Sixth Street	belong grade				
Ash	inspection	0.0	"	on south line	2'	X
Beech	"	6"	"	" " "	1' 6"	O.K.
Cedar	"	12"	"	" " "	1'	OK
Date	flush-tank			" " "	capacity)

street Seventh Street below grade

Street	Notes	Width	Location	Remarks
M				
L				
K	inspection	7"	"	on south line, under west Rail st. cap + neck 1' 5" OK
J	"	12"	"	" " " " " 10" OK
I	"	10"	"	" " " " " 10" OK
H	"	6"	"	" " " " 3' south of property 1' OK
G	"	14"	"	on south line 2' 4" X
F	"	9"	"	" " " " 11" OK
E	"	1' 2"	"	" " " " 8" OK
D	"	9"	"	" " " " 1' OK
C	"	3"	"	" " " " 1' 8" OK
B	"	5"	"	" " " " 1' 6" X

street Seventh Street
A inspection below grade
1' 1" "

Ash " 6" "

Beech " 8" "

Cedar " 9" "

Date flush-tank

on south line 10" OK

4' south of property 1' 2" OK

3" " " " 1' 3" OK

on south line 2' ~~5"~~ X

capacity

Street	Eight Street	below grade				
N						
M	inspection	0.0	"	on south line	1'	OK
L	manhole	4"	"	on west line of 8th St on main line		OK
K	inspection	0.0	"	on south line	1'4"	OK
J	"	4"	"	" " "	1'5"	OK
I	"	0.0	"	" " "	1'0"	OK
H	"	4"	"	" " "	1'1"	OK
G	"	5"	"	" " "	1'8"	OK
F	"	0.0	"	" " "	2'11"	X
E	"	0.0	"	" " "	2'6"	X
D	"	0.0	"	" " "	2'11"	X
C	"	1'10"	"	" " "	6"	OK

street	Eight Street	below grade			
B	inspection	0.0	"	on south line	2' 0" X
A	"	3"	"	" " "	1' 3" OK
Ash	"	10"	"	" " "	1' 0" OK
Beech	"	0.0	"	" " "	1' 2" OK
Cedar	"	6"	"	" " "	1' 1" OK
Date.	flush-tank			25' south of property (capacity)

Street Ninth Street below grade

N					
M					
L	flush tank			(capacity)	
K	inspection	9" "	on south line	1'3" OK	
J	"	1'1" "	" " "	1'2" OK	
I	"	8" "	" " "	1'8" OK	
H	"	8" "	" " "	1'6" OK	
G	"	11" "	" " "	1'8" X	
F	"	8" "	" " "	1'0" OK	
E	"	1'1" "	" " "	1'4" OK	
D	"	8" "	5' south of property	1'1" OK	
C	"	9" "	on south line	1'3" OK	

Street	Ninth Street	below grade	on south line		
B	inspection	8" "		2"	X
A	"	0.0 "	" " "	2'3"	X
Ash	"	1'2" "	" " "	1'4"	OK
Beech					
Cedar	"	1'2" "	" " "	1'0"	X
Date	flush-tank		" " "	(capacity))

Street	Tenth Street	below grade				
N						
T						
M	inspection					
L	flush tank	-			on south line (capacity))
K	inspection	6"	"	"	"	2'0" X
J	"	6"	"	"	"	1'0" OK
I	"	4"	"	"	"	1'4" OK
H	"	5"	"	"	"	1'3" OK
G	"	3"	"	"	"	1'6" OK
F	"	0.0	"	"	"	1'8" OK
E	"	3"	"	"	"	1'3" OK
D	"	3"	"	"	"	1'7" OK
C	"	6"	"	"	"	1'4" OK

Street	Fenth Street	below grade			
B	inspection	9"	"	on south line	1'2" OK
A	"	0.0	"	" " "	1'6" OK
Ash	"	3"	"	" " "	1'0" OK
Beech	"	3"	"	" " "	1'2" OK
Cedar	"	0.0	"	" " "	1'2" OK

Date flush tank

(capacity)

street	Eleventh Street	below grade			
N	inspection	8"	"	west line of 11 th St	1' 10" OK
M	"	0.0	"	on south line	3' 6" X
L	glass tank			" " " (capacity))
K	inspection	2"	"	" " "	1' 6" X
J	"	0.0	"	" " "	1' 6" OK
I	"	2"	"	" " "	1' 8" OK
H	"	0.0	"	" " "	1' 5" OK
G	"	2"	"	" " "	1' 0" OK
F	"	12"	"	" " "	1' 4" OK
E	"	6"	"	" " "	2' 0" X
D	"	2"	"	" " "	1' 8" OK
C	"	6"	"	" " "	1' 2" X

Street Eleventh Street below grade

B inspection 10" "

A flush-tank

in south line 2'0" X

(capacity)

Street Twelfth Street below grade

N						
M	inspection	6"	"	4' south of property	1'4"	OK
L	flush-tank					
"	man-hole	3"	"	south line street capacity		
K	inspection	2"	"	on west line of 12th St	1'0"	OK
				on south line		OK
J	"	4"	"	" " "	1'0"	OK
I	"	2"	"	" " "	1'4"	OK
H	"	4"	"	" " "	1'0"	OK
G	"	2"	"	" " "	1'6"	OK
F	"	0.0	"	" " "	1'3"	OK
E	"	4"	"	" " "	1'4"	OK
D	"	4"	"	" " "	1'0"	OK

TD

Street	Twelfth Street inspection	below grade	on south line	1'0" OK, K
C	"	6" - "	" " "	OK, K
B	"	0.0 "		OK, K
A	flush tank		capacity)

street Thirteenth Street below grade

N	inspection	4"	"	on west line of 13th St	1' 0" OK
M	"	0.0	"	on south line	1' 0" OK
L	flush-tank			" " " capacity)
K	inspection			<u>not built</u>	
J	"	0.0	"	on south line	1' 5" OK
I	"	6"	"	" " "	1' 2" OK
H	"	0.0	"	" " "	1' 0" OK
G	"	4"	"	" " "	1' 0" OK
F	flush tank	0.0	"	on south line	F st (capacity)
	flush tank	0.0	"	" " "	F st (")
E	inspection	0.0	"	" " "	1' 1" OK
D	"				

street Thirteenth Street below grade

C inspection 0.0 "

B " 0.0 "

A flush-tank

on south line 1' 1" OK

" " " 1' 0" OK

(capacity)

Street St Fourteenth Street below grade

N inspection 1' 0" " 8' East of west line of 14th 1' 0" OK

M " flush-tank 0.0 " on south line 1' 10" OK
capacity

L

K man hole 10" " on south line OK

J " 8" " " " " " OK

I inspection 0.0 " " " " " 1' 0" OK

H { flush-tank on south line H. St (capacity)

" " on north " " " (")

G inspection on East line of 14th (")

F " 0.0 " on south line 1' 3" OK

E " 12" " " " " " 1' 6" OK

D

street Fourteenth Street below grade

C

B

A flush tank

capacity

Street Fifteenth Street below grade

N inspection

M " " 0.0 " on south line 8" OK

L flush tank
man-hole on main line " " " capacity

K

J

I

H manhole

G

F " "

E manhole

OK

D inspection
flush tank

0.0 "

on south line 1' 0" OK
on west of 15th st capacity

57 street Fifteenth Street below grade

C inspection 8" "

on south line 1'1" OK

B " 6" "

" " " 1'1" OK

A flush tank

(capacity)

Street Sixteenth Street below grade

N inspection

M flush tank
inspection

L large flush tank

K

J

I

H

G inspection

6" "

on south line

1'5" OK

F "

12" "

" " "

2'0" OK

E

D inspection

0.0

1'
1'5" OK

west line of 16th St

st street Sixteenth Street below grade

C inspection 0.0 " on south line 1'2" O.K

B " 0.0 " " " " 1'0" O.K

A. flush tank (capacity)

St street Seventeenth Street belongrate

N

M man-hole

L inspection

0.0

"

on south, line

1' 5" OK

K

"

0.0

"

" " "

1' 0" OK

J flush-tank

"

" " " capacity

" " "

"

on north line "

I inspection

0.0

"

13' North of property

1' 2" OK

H

"

G

"

0.0

"

on south, line

1' 4" OK

F

"

E flush-tank

on south line capacity

" " "

on north line "

D

"

S. Street Seventeenth Street below grade

C inspection

B " " 0.0 " " on south line 1' 1" O/K

A flash tank " " " capacity.

street Eighteenth Street below grade

Letter	Description	Depth	Notes	Location	Remarks
N	man-hole	0.0	"	on west line of 18th	OK
M	inspection	0.0	"	on south line	1' 3" OK
L	"	4"	"	" " "	1' 0" OK
K	"	2"	"	" " "	1' 0" OK
J	flush-tank	0.0	"	" " " capacity	
"	"	0.0	"	on north line	"
I	inspection	4"	"	on ^{north} south line	2' 2" X
H	"				
G	"	8"	"	on south line	2' 4" X
F	"	0.0	"	" " "	2' 6" X
E					
D	flush-tank	0.0	"	" " " capacity	

street Eighteenth Street below grade

C inspection

B " under can
track "

A flush tank

on south line capacity

street Nineteenth Street below grade

N	inspection	0.0	"	on west line 19th	1' 4" OK
M	"	3' 6"	"	on south line	1' 0" OK
L	"	6"	"	" " "	1' 0" OK
K	"	3"	"	" " "	1' 0" OK
J	"	0.0	"	" " "	1' 0" OK
I	flush-tank	0.0	"	" " " capacity	
H	inspection				
G	"	2'	"	on south line	10" OK
F	"	18"	"	" " "	1' 2" OK
E	"	0.0	"	" " "	1' 1" OK
D	flush tank			" " " capacity	
"	"			on north line	"

street Nineteenth Street below grade

C inspection

B

A

Sheet Twentieth Street below grade

N	inspection	0.0	"	on west line of 20th	1' 4" OK
M	"	1' 10"	"	on south line	0' 10" OK
L	"	0' 8"	"	" " "	1' 6" OK
K	"	1' 0"	"	" " "	1' 0" OK
J	flush tank	0.0	"	" " " capacity	
I	" "	0.0	"	on north line	"
I	inspection	0.0			
H	"	1' 1"	"	on south line	1' 0" OK
G	"	1' 6"	"	" " "	1' 0" OK
F	flush tanks	0.0	"	" " " capacity	
"	" "	0.0	"	on north line	"
E	inspection	8"	"	" " "	1' 3" OK
D	" "	4"	"	" " "	2' 0" OK

Street Twentieth Street below grade

C inspection

B

A

the street Twenty-first Street below grade

C	N	inspection	0.0	"	on west line 21st st	2' 8" X
I	M	"	10"	"	on south line	1' 2" OK
I	L	"	3"	"	" " "	1' 0" OK
K		"	4"	"	" " "	1' 4" OK
J		flush tanks	0.0	"	" " " capacity	
"		" "	0.0	"	on north line	"
I		inspection	6"	"		1' 0" OK
H		inspection	6"	"	on south line	1' 0" OK
G		"	10"	"	" " "	10" OK
F		flush tanks	0.0	"	" " " capacity	
"		" "	0.0	"	on north line	"
E		inspection	6"	"	" " "	10" OK
D		"	0.0	"	" " "	1' 2" OK

th street Twenty-first Street below grade

C	inspection	0.0	"	on west line of 21st 1' 1" OK
B	flush tank	0.0	"	on south line (capacity)
A				

street street Twenty-second Street below grade

C	N	inspection	0.0	"	on west line 22nd	2' 6" OK
B	M	"	0.0	"	on south line	1' 8" OK
A	L	inspection	0.0	"	on south line	1' 4" OK
	K	inspection	0.0	"	on south line	1' 0" OK
	"	flush tank	0.0	"		capacity.
	J	inspection	0.0	"	on south line	1' 6" OK
	"	flush tank	0.0	"		capacity
	I	inspection	0.0	"	on south line	1' 5" OK
	H	"	12"	"	" " "	1' 0" OK
	G	"	4"	"	" " "	1' 6" OK
	F	"	1' 10"	"	" " "	1' 6" OK
	E	"	2"	"	" " "	1' 2" X
	D	flush tanks	0.0	"	" " "	capacity
	"	"	0.0	"	on north line	"

street Twenty-Second Street below grade

C inspection 0.0 " on west line 22nd. 10" OK

D flush-tank 0.0 " on south line capacity

A

street Twenty-third Street below grade

G inspection

F " 6" 0" " on south line 1' 0" OK

E " 1' 7" " " " " 1' 7" X

D " 10" " " " " " 1' 6" X

C " 6" " " " " " 1' 0" OK

D flush tank 0.0 " " " " (capacity)

A

street Twenty-fourth Street below grade

N						
M	inspection	0.0	"	on south line	2' 0"	OK
L	"	0.0	"	" " "	2' 4"	X
K	"	0.0	"	" " "	2' 4"	OK
J	"			not built		
I	"	0.0	"	on south line	1' 5"	OK
H	flush tank inspection	0.0	"	" " "	(capacity) 1' 6"	OK
G	inspection	0.0	"	" " "	1' 6"	OK
F	"	0.0	"	" " "	1' 8"	OK
E	"	4"	"	" " "	1' 2"	OK
D	"	10"	"	" " "	1' 0"	OK

Street Twenty-fourth Street below grade

C inspection 6" "

on south line 1'0" OK

B flush tank 0.9 "

" " " capacity

A


the

C

D

A

7



74 Tanks empty after
days
65 " " day